3COM CORPORATION
IMPACT (3C861, 3C862)

Card Type	ISDN TA
Processor	Motorola 68302
Processor Speed	20MHz
Chip Set	Siemens 2081
Maximum Onboard Memory	1MB DRAM
Transfer Rate	56Kbps x 2/64Kbps x 2
Data Bus	16-bit ISA
ISDN Protocol	V.120, PPP
Switch Type	5ESS, DMS100, EWSD, NI-1
Error Correction/Compression	STAC
Card Size	Full-height, full-length

CONNECTIONS	
Function	**Label**
ISDN interface	CN1

USER CONFIGURABLE SETTINGS
All jumpers on the card are factory configured and should not be altered.

DIAGNOSTIC LED(S)			
LED	**Color**	**Status**	**Condition**
LED	Unidentified	On	ISDN connection is good
LED	Unidentified	Off	ISDN connection is broken